

# Oil Field Environmental Incident Summary

**Incident:** 20150518103739      **Date/Time of Notice:** 05/18/2015 10:37

**Responsible Party:** QC Energy Services

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** LK-OBRIGEWITCH 146-97-3427H-2

**Field Name:** LITTLE KNIFE

**Well File #:** 22798

**Date Incident:** 5/17/2015

**Time Incident:** 10:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 146

**Rng:** 97

**Sec:** 34

**Qtr:** SE

**Location Description:**

**Submitted By:** Jason Henry

**Received By:**

**Contact Person:** Luke Wolf  
10454 1st Street SW  
Killdeer, ND 58640

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.6 Mile

**Distance Nearest Water Well:** 0.6 Mile

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1.3	Barrels				

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

The source of the release was secured immediately upon discovery of the incident.

**Areal Extent:**

N/A - the release remained on the location.

***Potential Environmental Impacts:***

The release occurred above ground and remained on the well location. The impacted soil will be excavated and transported off-site for proper disposal.

***Action Taken or Planned:***

The impacted soil will be excavated and transported off-site for proper disposal.

***Wastes Disposal Location:*** At a properly permitted disposal facility.

***Agencies Involved:***

***Updates***

---

***Date:*** 5/18/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill remained on location. NDIC retains oversight.